

Load Monitor (Load Cell 100t & 250t)

NEW SELBER LOAD MONITOR



Load Monitor RM-7414

OUTLINE

Load cell for pres maintenance & strain gauge sensor calibration.

※Load Cell

Model: RS-711H (100t)
RS-712H (250t)



Load Cell
RS-711H (100t)

Load Cell
RS-712H (250t)

Characteristic

- Best suitable for load measurement. Max. to 1000t available.
4 pcs of RS-711H(100t) and max to 400t.
4 pcs of RS-712H(250t) and max to 1000t.
- Memories max 5 kinds of setting.

Load Monitor
Case



Load Cell (100t)
Case



Load Cell (250t)
Case



- Manufacturer

株式会社理研計器奈良製作所

〒633-0054

49-1 Abe, Sakurai, NARA, Japan
TEL.0744-43-0051 FAX. 0744-43-0056
Sales Engineering Department